

75-25 153 Street, Queens, 11367

Generated on 02/21/2024

**Applied Filter/Search**

SEARCH CRITERIA (SR NUMBER, COMPLAINT ID OR APARTMENT NUMBER)

ph11

Complaints (17)

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
1	311-17542310	02/06/2024	12733283	PH11	MOLD
	COMPLAINT DETAIL	LOCATION	STATUS		
	N/A	ENTIRE APT	Open		

STATUS DESCRIPTION

The following complaint conditions are still open. HPD may attempt to contact you to verify the correction of the condition or may conduct an inspection.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
2	311-17542310	02/06/2024	12733283	PH11	DAMP SPOT
	COMPLAINT DETAIL	LOCATION	STATUS		
	FROM WALL/CEIL	LIVING ROOM	Open		

STATUS DESCRIPTION

The following complaint conditions are still open. HPD may attempt to contact you to verify the correction of the condition or may conduct an inspection.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
3	311-17160237	01/04/2024	12634576	PH11	MOLD
	COMPLAINT DETAIL	LOCATION	STATUS		
	N/A	ENTIRE APT	Closed		

75-25 153 Street, Queens, 11367

Generated on 02/21/2024

**STATUS DESCRIPTION**

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
4	311-17028386	12/22/2023	12609964	PH11	MOLD
	COMPLAINT DETAIL	LOCATION	STATUS		
	N/A	ENTIRE APT	Closed		

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
5	311-17028386	12/22/2023	12609964	PH11	DAMP SPOT
	COMPLAINT DETAIL	LOCATION	STATUS		
	FROM WALL/CEIL	LIVING ROOM	Closed		

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
6	311-17028386	12/22/2023	12609964	PH11	DOOR FRAME
	COMPLAINT DETAIL	LOCATION	STATUS		
	FRAME BROKEN	LIVING ROOM	Closed		

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

75-25 153 Street, Queens, 11367

Generated on 02/21/2024



S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
7	311-16993889	12/19/2023	12597440	PH11	ROOFING

COMPLAINT DETAIL	LOCATION	STATUS
LEAKING	ROOF	Closed

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
8	311-16993889	12/19/2023	12597440	PH11	ROOF DOOR/HATCH

COMPLAINT DETAIL	LOCATION	STATUS
NO SELF-CLOSING	ROOF	Closed

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
9	311-16913446	12/12/2023	12581245	PH11	VENTILATION SYSTEM

COMPLAINT DETAIL	LOCATION	STATUS
BRKN OR MISSING	BATHROOM	Closed

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

75-25 153 Street, Queens, 11367

Generated on 02/21/2024



S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
10	311-16913395	12/12/2023	12581196	PH11	FLOOR

COMPLAINT DETAIL	LOCATION	STATUS
BRKN/DEFECTIENTIRE APT VE		Closed

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
11	311-16913270	12/12/2023	12581179	PH11	DAMP SPOT

COMPLAINT DETAIL	LOCATION	STATUS
FROM WALL/CEIL	ENTIRE APT	Closed

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
12	311-16908462	12/12/2023	12580163	PH11	MOLD

COMPLAINT DETAIL	LOCATION	STATUS
N/A	ENTIRE APT	Closed

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

75-25 153 Street, Queens, 11367

Generated on 02/21/2024



S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
13	311-16889916	12/10/2023	12576646	PH11	MOLD
	COMPLAINT DETAIL	LOCATION	STATUS		
	N/A	ENTIRE APT	Closed		

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
14	311-16729941	11/27/2023	12523148	PH11	WINDOW FRAME

COMPLAINT DETAIL	LOCATION	STATUS
LOOSE/DEFEC TIVE	LIVING ROOM	Closed

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
15	311-16729941	11/27/2023	12523148	PH11	HEAVY FLOW

COMPLAINT DETAIL	LOCATION	STATUS
AT WALL/CEIL	LIVING ROOM	Closed

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. Violations were issued. Information about specific violations is available at www.nyc.gov/hpd

75-25 153 Street, Queens, 11367

Generated on 02/21/2024



S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
16	311-16729941	11/27/2023	12523148	PH11	MOLD
	COMPLAINT DETAIL	LOCATION	STATUS		
	N/A	ENTIRE APT	Closed		

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.

S.No.	SR NUMBER	COMPLAINT DATE	COMPLAINT ID	APT #	COMPLAINT CONDITION
17	311-16675052	11/21/2023	12488700	PH11	MOLD
	COMPLAINT DETAIL	LOCATION	STATUS		
	N/A	ENTIRE APT	Closed		

STATUS DESCRIPTION

The Department of Housing Preservation and Development inspected the following conditions. No violations were issued. The complaint has been closed.